



STEAMDOSS

RELEASE NOTES:

- A new updated version of STEAMDOSS has been released on 01/20/07.
- Heat and power simulation module is displayed as “process flow” tab and in help menu .Design program is displayed as “design utility” tab in module and help menu
- Current known bugs based on feedback and comments are as given below (Updated on 03/12/07)

Item Number	STEAMDOSS module	Resolution number	Reported bugs	Comments
1	Design programs	0700072307	In Combustion, economizer and fuel properties design programs, results need to display additional decimals as few results with "0" contain additional decimals which are not displayed	Will be updated
2	Design programs	0800072307	Payback design program works only when the investment is higher than revenue and for single investments	Will be updated
3	Design programs	0900031207	Payback Crystal report gives a display error of report	Will be updated
4	Design programs	1000031207	Combustion program fuel heat value is displayed a zero value some times	Will be updated
5	Heat and power simulation module	0600260704	Occasionally, Branch Component does not appear automatically on screen when placed on the screen	To resolve , Click "Refresh" button if branch components do not appear

6	Heat and power simulation module	0600460704	Additional validation needed for branches and piping components listed in limitations of simulation module (process flow in help menu)	1) Please see the limitation on branches 2) model in steps and verify results in each step.
7	General	0110031207	The program throws unhandled exception while using in European countries	Ensure the Regional setting is changed to US systems and English keyboard is used
8	General	0120031207	Start up form is stalled when Register now button or cancel button is pressed some times	To remove the form, please go to Task manager and end the process if it is stalled. This issue will be resolved in next update.